

7/1-1


# CORNER RECORD

Document Number 97-242

City of RIVERSIDE

County of RIVERSIDE, California

Brief Legal Description LOT 6/7, M.B.228/42-43, IN SE 1/4 SE 1/4 SEC.1, T.3 S., R.5 W., S.B.M.  
(Include: Sec., Twp., Rge., and Meridian or Rancho)



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey 2/13/96

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT ON PAGE 2


A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SEE PLAT ON PAGE 2

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 18 1996.


Signed Joseph N. Beeler L.S. or R.S. Number 4055



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 3 1997 and examined and filed Aug 13 1997.

Signed D. W. Beecroft Title Senior L.S.



County Surveyor's Comment \_\_\_\_\_

THE FILING OF THIS CORNER RECORD  
DOES NOT RELIEVE THE SURVEYOR  
FROM ANY RESPONSIBILITY OF THE  
FILING OF A RECORD OF SURVEY